



☐ **Head Office**
8701 - 102 Street
Clairmont, AB T8X 5G8
Bus: (780) 532-7350
Fax: (780) 532-7769

Pro-Pak

Crate 4

For a complete list of operation centers visit: www.ipacservices.com

11121 - 40/1390 (3/8 X 2 (w/Nut & washer) Q: 4
11121 - 40/1410 (3/4 X 2 (w/Nut & washer) Q: 2
11147 - 10/11 (Toolbox) Q: 1
11147 10/60 (26" 150 graffoil gasket) Q: 4
11147 10/80 (1 1/4 X 3 Cw Nut & washer Q: 96
11147 20/30 (26" 150 graffoil gasket) Q: 1
11148 10/50 (20" 150 graffoil gasket) Q: 1
11148 10/70 (1 1/8 X 2 3/4 (w/Nut & washer) Q: 20

P111

[REDACTED] Q: 1 3578

11148 20/70 (1 1/8 X 2 3/4 Cw Nut & washer) Q: 20

3576

11148 30/40 (1 1/4 X 3" Cw N & w) Q: 72
11148 40/100 (graffoil GHE-3) Q: 1
11148 40/110 (graffoil GHE-3) Q: 2
11161 3/50 (3/8 X 2 bolts SP#27A) Q: 8
11161 3/60 (3/8 X 2 bolts SP#33A) Q: 8
11161 3/70 (5/8 X 3 3/4 B7 Studs & Nuts) Q: 16
11161 3/80 (3/4 X 3 3/4 B7 w/ nuts) Q: 8
11161 3/90 (1 1/2" 300 gaskets 304SS) Q: 2
11161 3/100 (2" 300 gaskets 304SS) Q: 2
11161 3/120 (4" 150 gaskets 304SS) Q: 1
11161 3/130 (5/8 X 3 1/2 B7 studs w/ nuts) Q: 8
11161 3/180 (3/8 X 2 bolts SP#22A) Q: 8
11161 3/190 (3/8 X 2 bolts SP#28A) Q: 8
11161 3/240 (Exhaust bellows) Q: 1
21147 10/70 (455 OD X 348 graffoil) Q: 2
21147 20/30 (26" 150 graffoil) Q: 1

3573

3577