

INSPECTION REPORT

Customer:	P.O. No:
Inspected By:	W.O. No:
RIG #: Unit #18	Contractor:
Location: Brooks	Page 2 of 3
Type of tool: Portable Test Vessel	I.P.I.A No: 6511
Type of Inspection: Ultrasonic Wall Thickness	

Back



1.224

1.226

1.239



1.233



1.248
Front

1.221

1.229



1.210

1.211

INSPECTED BY:
DATE: April 14 th 2024